

FAKULTI SENIBINA, PERANCANGAN DAN UKUR**JABATAN SENIBINA DALAMAN****November 2006**

Prepared By:

FAZLIN BINTI AWALUDIN**2003361603****title****REPORT****PROPOSED UPGRADING KINDERGARTEN FOR DZULIMAN AT NO 20
TRONOH INDAH 1,
31250 TRONOH,PERAK**


Accepted by fulfill apart of term And condition to Graduate in

Diploma Interior Design

Supervisor : MR OTHMAN BIN MD NOR

Coordinator : CIK MAWAR MASRI

Course Coordinator : PROF MADYA RUSNI

Othman Mohd Nor*Pensyarah*Jabatan Senibina Dalaman
Fakulti Senibina Perancangan dan Ukur
Universiti Teknologi MARA Perak

ABSTRAK

In order to get a good design a lot of research has to be done. From observation itself can ensure self experience to undergo certain project, whether it is for exterior or interior

Suitable elements are important to produce certain project to get suitable concept and images. By doing so, a proper concept will be implemented. As the results, a maximum satisfaction for end user

A Khalifah Kindergarten is proposed to be an example of the maximized utilization of modern learning technology and traditional Islam. In this development center the goal would be to showcase an ideal learning and Islamic environment. This idealized example could then serve as a model for the creation of other development centers implementing this idealized program. It would be the beginning of a research facility to investigate new educational techniques and curricula appropriate to Islam.

ACKNOWLEDGEMENT

ABSTRAK

LIST OF DIAGRAM

LIST OF SCHEDULE

	Content	Pages
CHAPTER	1.0 INTRODUCTION	2 - 20
	1.1.1 ISSUES	
	1.1.2 OBJECTIVES	
	1.1.3 AIM	
	1.1.4 SCOPE OF PROJECT	
	1.1.5 METHODOLOGY	
1.2	CLIENT	
	1.2.1 BACKGROUND	
	1.2.2.1 HISTORY	
	1.2.2.2 ADSRESS	
	1.2.2.3 CHART	
	1.2.2 LOGO	
	1.2.2.1 CORPRATE COLORS	
	1.2.2.2 MISSION / VISION	
CHAPTER	2.0 PROJECT	21-62
	2.1 INTRODUCTION	
	2.1.1 CLIENT REQUIREMENT	
	2.1.1.1 SPATIAL	

2.1.1.2 FACILITIES REQUIREMENTS

2.1.1.3 AIDS REQUIREMENTS

SCOPE OF WORK

2.1.2.1 EXTERIOR

2.1.2.2 INTERIOR

2.1.2.3 SURROUNDING

2.2 CASE STUDY

2.2.1 CASE STUDY 1

2.2.1.1 ADDRESS

2.2.1.2 EXISTING PLAN

2.2.1.3 INTERIOR

2.2.1.4 AIR – COND AND LIGHTING

2.2.2 CASE STUDY 2

2.2.2.1 ADDRESS

2.2.2.2 EXISTING

2.2.2.3 INTERIOR

2.2.2.4 LIGHTING

2.2.4 CONCLUSION

2.3 SITE ANALYSIS

2.3.1 LOCATION

2.3.1.1 KEY PLAN

2.3.1.2 LOCATION PLAN

2.3.2 DRAWING

2.3.2.1 EXISTING

2.3.3 SITE ANALYSIS

2.3.3.1 FREQUENTS OF USAGE

2.4. EXISTING PLAN

2.4.1 SUN AND WIND ORIENTATION

2.4.1.1 SURROUNDING BUILDING